HONDA **Service Bulletin** **04-009**

Applies To: **ALL MODELS** **February 17, 2004**

Updating the Honda Interface Module (HIM) Model 3557-0100-00

(This bulletin is no longer valid as of July 24, 2008; information is obsolete.)

© 2004 American Honda Motor Co., Inc. – All Rights Reserved

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.